


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
This is not an original GLO corner.

Index File No. T-18



Description of corner evidence found:  
No corner monument or evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by subdivision.  
Set 2.5"x30" aluminum capped aluminum pipe rising 8" above ground. Set steel fence post 3.0 ft. south of corner.

T5S R35E  
C  $\frac{W \ 1/16}{S \ 26}$  C  
RLS 1844  
1985

New BT's:  
9" Tamarack bears N00.5°E, 64.3 ft.,  
blazed & scribed: CW 1/16 S26 BT.  
7.5" Fir bears N61°E, 17.4 ft.,  
blazed & scribed: CW 1/16 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is in timber 50 ft., S70°W from fence corner. Take Road 51 to Road 5155, 0.2 miles to Road 5100-240, then north to fence and west to cap.

Compass Declination: 19 1/2°E  
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 5, 1985



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY SURVEYOR**  
Date Received 9-18-85  
Date Filed 9-23-85  
By G. LANGLITZ DEPUTY  
File No. 72-85 R