CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishments

Original survey by General Land Office contract survey 1882

The original notes state. Set a post from which; A pine 32" in diam bears N27°W 40 lks dist marked $SC_{\psi}^{1}SBT$; A pine 28" in diam bears N77°E 20 lks dist marked $SC_{\psi}^{2}SBT$;

7-3		
DIAGRAM	R35EWM	
SS 31 S3		

Description of corner evidence founds

A pine 32" in diam bears N77°E 20 lks dist with scribe. Now good. At N27°W found a down log with scribe.

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 2^n galvanized pipe 30^n long with bronze cap on top and 8^n plate welded to bottom. The pipe set to a depth of 20^n and back filled with stone and tamped soil.

I stamped the disk.

S‡cor T5S R35E

S31 S3 ORE LIC 381 1969

From the monument the bearing tree is.
A pine 32" in diam bears N770E 20 lks dist.

I set the following new bearing tree;
A tamarack 6" in diam bears N32°W 25 ft dist marked with a scribe ‡SBT
and measured to center of tree. I set a steel fence post with USFS sign 54-4 attached.
USFS National Forest boundary sign was placed on the nost indicating National
Forest land to South. USFS bearing tree signs were placed on the bearing trees shoulder high facing the monument.

Office of County surveyor	County of Union	UNION COUNTY
State of Oregon , I hereby certific for record on the 20 day of Sapt	fy that the within instrument was file	P.m., (signed)
(COUNTY OFFICIAL)	(((((((((((((((((((
	,	Date Filed
		File No. 629-84R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-03

DIAGRAM

T5S R35E SC 1/4_{*}S31

History of original corner establishment:

The original survey of the Standard Parallel along the south boundary of T5S, R35E was by J. Cooper, under Contract No. 397, approved April 5, 1882. At this corner he set a post, from which a 32" Pine bears N27°W, 40 lks. and a 28" Pine bears N77°E, 20 lks.

Description of corner evidence found:

Found 3" brass cap on 2" I.D. iron pipe. Cap is stamped:

Bearing trees found:

A 7" Tamarack bears N30°W, 24.8 ft., healed blaze. (Record bearing: N32°W)

A 32" P. Pine bears N81°E, 14.1 ft., healed blaze. (Record bearing: N77°E)

T5S R35E s,31 s3 T6S ORE LIC 381

1969

S 1/4 COR

* LS 381 cap is stamped incorrectly. It should be stamped with SC at the top. S3 and T6S should not be on it.

Corner by LS 381 is recorded on document #629-84R with the Union

Description of monument and accessories I established to perpetuate the original location of this corner:

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 150 ft. west of road at fence at west side of top of ridge.

I hereby certify the above described corner monument and/or accessories was established as described on August 1, 1984.

UNION COUNTY SURVEYOR	
Date Received 10-17-84	
Date Filed 10-24-84	
BY G. LANGLITZ DEPUTY	
File No. 991-84R	

PROFESSIONAL LAND SURVEYOR
David E. Scott
OREGON JULY 13, 1979 DAVID E. SCOTT 1844

REGISTERED

Office of	County of
State of	At the within income
(COUNTY OFFICIAL)	······ , 19
	(DEPUTY)