History of original corner establishments

Original survey by General Land Office contract survey 1881.

Original notes state; Set a post for standard corner to section 31 and 32 from which

A tamarack 20" in diam bears N81°E 108 lks dist. marked T5S R35E S32BT; A tamarack 20" in diam bears N58°W 159 lks dist marked T5S R35E S31 BT;

ま- 5			
DIAGRAM			
S Cor.T5SR35EWN			
31 32			
2			

Description of corner evidence founds

The bearings and distance would not intersect exactly. We used the bearing s of trees. Found A tamarack 25th in diameter bears N81°E 76.3 ft. A tamarack 23th in diam bears N58°W 105.7 ft. Both bearing trees are in good condition.

REGISTERED OREGON LAND SURVEYOR

> MAY 4, 1956 JAMES G. VOELZ 381

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner so determined I set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 20" and back filled with stone and tamped soil .

I stamped the disk.

S COR T5S R35E S31 S32 T6S S2 ORE LIC 381 1969

From the monument the original bearing trees are; A tamarack 25" in diam. bears N81°E 76.3 ft. A tamarack 23" in diam bears N58°W 105.7 ft.

I set an additional bearing tree as follows.

A black pine 9 in diam bears S32 W 47.8 ft. dist marked T6S R35E S2BT;

Distance measured to center of respective trees. I marked the new tree with a scribe.

I set a steel fence post with USFS sign attached. USFS National Forest boundary sign was attached to post indicating National Forest land to South. USFS bearing tree signs were placed on the bearing trees shoulder high facing the corner.

ffice of County surveyor Oregon , I hereby con Frecord on the 17 day of Sept	ify that the within instrum 60	Union COUNTY COUNTY
County surveyor	by January	PUTY) Date Received
		Date Filed
	en e	By

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original survey of the Standard Parallel along the south boundary of T5S, R35E was by J. Cooper, under Contract No. 397, approved April 5, 1882. At this corner he set a post from which a 20" Tamarack bears N81°E, 108 lks. and another 20" Tamarack bears N58°W, 169 lks.

Index File No. Z-05 **DIAGRAM** T5S R35E SC 31 | 32

Description of corner evidence found:

Found a 3" brass cap on 2" iron pipe. Cap stamped:

Bearing trees found:
A 25" Tamarack, dead, bears N54°W, 104.2 ft., healed blaze.

A 27" Tamarack bears N81°E, 76.3 ft., healed blaze.

S COR T5S R35E T6S S31 S32

ORE LIC 381 1969

Corner by LS 381 recorded on document #630-84R with Union Co. Surveyor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set one new BT, an 8" P. Pine bearing N44°W, 112.4 ft., blazed and scribed: SC T5S R35E S31 BT.

Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is 30 ft. south of fence along edge of clearing line, 400 ft. east of Road 5160-141.

I hereby certify the above described corner monument and/or accessories was established as described on August 1, 1984.

	UNION COUNTY SURVEYOR	REGISTERED
	Date Received 10-17-84 Date Filed 10-24-84 By G. LANGLITZ, DEPUTY File No. 992-84R	PROFESSIONAL LAND SURVEYOR OREGON JULY 13, 1979 DAVID E. SCOTT 1844
Office of	County of	filed in this office
(COUNTY OFFICIAL)	by	