CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None, corner established this survey.

R-16 DIAGRAM T5S R37E E1/16 S S 27 PLS 1206 1987

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a $2\frac{1}{2}$ " x 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 24" into the ground, with a 36" dia. stone mound. Cap is marked as shown in the corner diagram.

From the corner point: (New BT's)
A 10" dia. Tamarack bears N. 28° W. at 21.4 ft. dist., mkd. E1/16 S 22 BT.
A 6" dia. L.P. Pine bears S. 11° W. at 16.2 ft. dist., mkd. E1/16 S 27 BT.

Set a steel fence post 5° West from the monument and attached USFS 54-2 and 54-9 signs. Painted the face of the blaze and a 6" band around the bearing trees red. Attached I.D. washer and USFS 54-9 and 54-3 signs to the bearing trees. Used $18\frac{1}{2}$ declination on a staff compass signs to the bearing trees. Used log declination on a stall compass for readings to the bearing trees. Used a steel tape to measure to a nail set in the side of the trees. The 3/4" dia. brass I.D. washer Was nailed between the B and T scribes.

This corner was monumented to USFS specifications on October 22,

1987, witnessed by Tom Fisk, Larry McBroom and Andy Marlette.

UNION COUNTY SURVEYOR

Office of County Surveyor County of Union State of ... Oregon , I hereby certify that the within instrument was filed in this office

.....by

Form R6-7100-57 (9/71)

(COUNTY DEFICIALL REGISTERED **PROFESSIONAL** LAND SURVEYOR

(DEPUTY)

GPO--798-276

ames do Hanke ORECON SEPTEMBER 21 1977

JAMES D. HANLEY 1206