
OREGON CORNER RESTORATION FORM

CORNER DESIGNATION

CONDITION REPORT

NOT FOUND
RENEWED
UNRECORDED

X SURVEYED IN REFERENCE OUT



PREVIOUS SURVEYS/RENEWALS

NONE

MONUMENTS & ACCESSORIES FOUND (CONDITION AND SOURCE)


FOUND TWO TREES WITH BLAZES (FOUND NO RECORD OF THESE TREES). THE NW TREE (17" PINE) HAD VISIBLE SCRIBES "1/16". THE SW TREE (22" PINE) HAD A BLAZE WITH NO VISIBLE SCRIBES.


MONUMENT SET (PROCEDURES AND DESCRIPTION)

SET 5/8" X 30" IRON ROD WITH 2 1/2" ALUMINUM CAP (MARKED AS SHOWN) AT MIDPOINT BETWEEN THE SECTION CORNER TO THE NORTH AND THE QUARTER CORNER TO THE SOUTH.

NEW ACCESSORIES

SET "OREGON STATE PARKS" TREE TAGS ON THE TWO FOUND BEARING TREES (SHOWN ON THE SKETCH).





LOCATION & COMMENTS

SOUTH OF STATE HIGHWAY 233 ON THE NORTHERLY SIDE OF A HILL, APPROXIMATELY 3/4 OF THE WAY TO THE TOP.

Die Hed 10/27/95

By R. ROBINSON, DENNY

FHO NO. 029-1995 R

OREGON PARKS & REC. DEPT. 1115 COMMERCIAL ST. NE SALEM, OREGON 97310 (503) 378-6821

PARTY CHIEF: RUSS PINARD NOTES: DEAN TIMMERMAN WITNESS: KEN SCHOENING REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16 1971
RUSSELL T. PINARD

Binara

EXPIRES 12-31-96