


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-09

History of original corner establishment:

The original subdivision of T6S R35 1/2E was by E. McCornack under Contract No. 398, approved January 9, 1883. Set a stone 14x12x8, from which a 12" Pine bears N85°E, 502 lks and an 8" Tamarack bears S30°E, 40 lks.



Description of corner evidence found:

No corner monument found.

Found one bearing tree, a 15" Tamarack bearing S30°E, 27.6 ft., blaze healed. (Origin unknown)

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

Cap is stamped: T6S
S35E R35 1/2E

S4		S9
S4		S9

RLS 1844
1984

New BT's:

A 6" Fir bears N83.5°E, 24.4 ft., blazed and scribed: T6S R35 1/2E S4 BT

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 400 ft. east of Rd 5160-056, 1500 ft. south from Road 5160-050.

I hereby certify the above described corner monument and/or accessories was established as described on September 4, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 10-17-84
Date Filed 10-24-84
By G. LANGLITZ DEPUTY
File No. 1015-84 R