History of original corner establishment:

Original survey by General Land Office contract wurvey 1882.

The original notes state; Set a post from which; A fir 14" in diam bears S57°E 54 lks. dist marked T6S R35E S2BT; A fir 30" in diam bears S77°W 33 lks dist marked T6S R35E S3BT;

DI	AGRAM		
F	rss RI sa	R35EWM	IV
Té	ss _s	[, S2	
	F5	F	2

Description of corner evidence found:

In section 3 found a down log with scribe.

REGISTERED
OREGON
LAND SURVEYOR

Auril Obel
MAY 4, 1956
JAMES G. VOELZ
381

CCOR T5S R35E S31

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the co ner I set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 20" and back filled with stone and tamped soil.

I stamped the disk.

Th original trees are in unsatisfactory condition.

From the monument the new bearing trees are;

A pine 8" in diam bears S23°E 23 ft. dist marked T6S R35E S2BT;

A tamarack 6" in diam bears S80°W 28 ft. dist marked T6S R35E S3BT;

A tamarack 22" in diam bears N32°W 7.6 ft. dist marked T5S R35E S3BT;

Distance measured to center of trees and marked with a scribe.

I set a steel fence post with USFS sign 54-4 attached. A National Forest boundary sign was attached to post indicating National Forest land to South.

USFS bearing tree signs were placed on bearing trees shoulder high facing the corner.

Office of County Surveyor	. County of	Union	1/2
State of I hereby reselfs	shoe sho sulship		ed in this office
County Surveyor (County Official)	by Jazz	(DEPUTY)	(algnes)

Form R6-7100-57 (9/66)

	UNIC S	N C	OUI	NTY L	
. na	nto Rece	eived_			
	te Filed		Na.	Depl	זיין
• Fi	e No.		(3		

The second

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner was established by H. Gradon, under Contract No. 499, approved November 24, 1884. At this corner he set a post, from which a 14" Fir bears S57°E, 54 lks. and a 30" Fir bears S77°W, 33 lks.

Index File No. A-17

DIAGRAM

T6S R35E

CC.

3 2

Description of corner evidence found:

Found 3" brass cap on 2" iron pipe set by LS 381 from evidence.

*Added letters (AM) to Brass Cap to reflect ammended status.

Found 21" Tamarack bearing N32°W, 7.6 ft. from original location, with healed blaze.

Previous corner certificate not on file.

C COR AM T5S R35E T6S S31 S3 S2 ORE LIC 381 1969

Description of monument and accessories I established to perpetuate the original location of this corner:

At true intersection point, I set a 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 8" above ground. Cap is stamped:
Steel fence post 3.0 ft. west of corner.
New BT's:

An 8" Tamarack bears S43.5°W, 41.4 ft., blazed and scribed: CC T6S R35E S3 BT.

A 6" Tamarack bears S1°E, 27.6 ft., blazed and scribed: CC T6S R35E S2 BT.

T5S R35E S31 S3 S2 T6S R35E CC RLS 1844

Brass LS 1844 disc in lower end of blazes.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 30 ft. south of fence and 36 ft. west of Road 5160-147.

I hereby certify the above described corner monument and/or accessories was established as described September 17, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of		
State of	SURVEYOR	
(DEPUTY)		

Form R6-7100-57 (9/71)

Date Received 10-17-84

10-24-84

Date Filed GPO-798-276

By G. LANGLITZ, DEPUTY
File No. 997-84 R