


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-23

History of original corner establishment:

The original subdivision of T6S, R35E was by Herman D. Gradon under Contract No. 499, approved November 24, 1884. This corner was not set by original subdivision.



Description of corner evidence found:

No corner monument or evidence found.

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>1000-84R</u>

Description of monument and accessories established to perpetuate the original location of this corner: Corner set by proportion.

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 4" above ground. Cap is stamped;

Set steel post 4.0 ft. north of corner.

New BT's:

A 6" Tamarack bears S79°W, 11.5 ft., blazed and scribed: 1/4 S1 BT.

An 11" Tamarack bears S2°E, 23.8 ft., blazed and scribed 1/4 S1 BT.

T5S R35E  
 -----  
 1/4 S1  
 T6S R35E  
 RLS 1844  
 1984

Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982

Compass Declination: 19 3/4°E      Witness: Duane Scott

Corner is found on northeast slope, 750 ft. east of Sheep Creek, Road 5160-090 to 5160-092, 0.9 mi. north of fence.

I hereby certify the above described corner monument and/or accessories was established as described September 5, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1979 DAVID E. SCOTT 1844

Office of..... County of.....  
State of..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)