CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

Index	File No.	D-4	-
	DIAGRA	W	
	and the second s	R38E	
	SE1/16-	S 6	

T6S R38E

Description of corner evidence found:

Not Set.

Corner is about 100' SW of track road in old skid road.

Description of monument and accessories I established to perpetuate the original location of this corner:

SE1/16 ·

At surveyed point set 1" X 36" galvanized pipe and brass cap marked: Set pipe 30" in the ground and placed mound of atone around to cap.

From which by magnetic declination of N20°E: A 10" Tamarac bears N21°W, 23.8 ft. scribed SE1/16S5 BT. A 10" Pine bears S55°W, 10.8 ft. scribed SE1/16S5 BT. Painted blazes red and 6" red band around. Placed location tags, Do Not Cut tags, and CZ property corner tags and brass washers stamped PLS 1051. Placed 54-4 on steel fence post 5' North of the corner.

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON OCT. 17, 1975 RY B. BARBOUR 1 0 5 1

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel T. Rowland Robert Boling

June 5, 1980

State of Oregon	within instrument was filed in . 19.8.0	MIDN CO BATY
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
orm R6-7100-57 (9/71)	Date Received	
		Date Filed
		Ву
		File No. 763-841