CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey of the 1st Standard Parallel South in Range 42 East by N.O. Walden, Contract No. 198, 1873:


Marked a Pine 6 inches diameter for corner to Sections

31, 32, 5 and 6, from which:

A fir 6 in. dia. bears N30°E dist. 18 links, A Pine 12 in. dia. bears N20°W dist. 32 links.

During subdivisions of T5S, R42E; "South between Sec. 31 and 32, ... Intersect S. boundary of the Township 464 links E. of the Standard Corner, ... From witness tree NE, I destroyed the "S32".

During subdivisions of T6S, R42E; North between Sec. 5 and 6, ... Intersect 1st Standard Parallel South 810 lks. W of Standard Corner.



Description of corner evidence found:

A ground depression with rotten wood at the location of the original corner tree.

From Which:

The original NE bearing tree, a 30" Douglas Fir alive and in fair condition, with previously opened and rehealed blaze visible, bears N30°E 11.9 ft. We open and find illegible scribing on an obliterated blaze at 12" depth in the tree,

No evidence remains for the original NW bearing tree.

Description of monument and accessories I established to perpetuate the original location of this corner:

UNION COUNTY SURVEYOR

Date Received 5-21-86

Date Filed 5-22-86

42

REGISTERED

PROFESSIONAL

LAND SURVEYOR

BREGON

GARY L. LANGLITZ

E

UNION COUNTY SURVEYOR

T5S

S31

S5

PLS 1099

1986

T6S

SC

BY G. LANGLITZ DEPUTY File No. 46-86 R

At the location of the orig. corner tree in the ground depression, we set a 2"x30" Aluminum Pipe, 28" in the ground with aluminum cap attached, marked:

From which:

The original NE bearing tree, previously described, bears N30°E 11.9 ft., (to blazed face) We mark new BT's as follows:

A 9" Grand Fir, scribed "SC T5S R42E S31 BT" on a double blaze bears N73°E 6.6 ft.

And a 15" Douglas Fir, scribed "SC T5S R42E S31 BT" on a double blaze bears N70°W 52.4 ft.

Attached brass washer marked "LS 1099" to lower blaze of new bearing trees.

Magnetic Compass (20° East Declination) Steel Tape

Corner is located on a moderate West slope, approximately 80 feet East of a dirt logging road.

May 18, 1986

Gary Langlitz, LS 1099, Deputy Union County Surveyor

Diane Langlitz Jeff Langlitz Staci Langlitz

Office of...... County of..... State of...... , I hereby certify that the within instrument was filed in this office by (COUNTY OFFICIAL) DEPUTY