CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None.

DIAGRAM T6S R42E E 1/16 S 18 1993 PLS 1106

)

See Survey 052-1994

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a $2\frac{1}{2}$ " X 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 28" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 & 54-2 to steel fence post, set 3.0 feet North of monument.

Set a steel fence post 3.0 feet South of corner also.

New bearing trees established: A 22" ponderosa pine bears N 19° E - 51.0 feet, scribed: C-E1/16S18BT. A 18" douglas fir bears S 10° E - 23.5 feet, scribed: C-E1/16S18BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 10, 1993.

Compass declination 18° East.

PROFESSIONAL LAND SUTVEYOR OREGON JULY 22, 1977 WILLIAM R. WELLS 11-94

REGISTERED

		1100
Office of	····· County of	renews 12-3
	hereby certify that the within instru	Whent was filed in this office
for record on the day of	UNION COUNTY	and the time of the
	SURVEYOR	
Form R6-7100-57 (9/71)	Deta Paraivad 11/3/94 Deta Paraivad 11/3/94 Dy Gryan T. Black File Mo 15/-1994 R	(DEPUTY) ◆(

GPO-591-971, 1988