## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None.

DIAGRAM T6S R42E 1993 PLS 1106

See Survey OSI-1994 Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a  $2\frac{1}{2}$ " X 30" aluminum pipe with a  $2\frac{1}{2}$ " aluminum cap, 29" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 to steel fence post, set 3.5 feet North of monument.

New bearing trees established:

A 26" ponderosa pine bears N 12° W - 92.7 feet, scribed: C1/4S19BT. A 17" ponderosa pine bears N 35° E - 89.9 feet, scribed: C1/4S19BT. A 21" ponderosa pine bears S 42° E - 40.1 feet, scribed: C1/4S19BT. A 17" ponderosa pine bears S 31° W - 63.0 feet, scribed: C1/4S19BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree. RIGISTERED

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 28, 1993.

Compass declination 18° East.

OREGON JULY 22, 197 WILLIAM R. WELLS

PROFISCI MAL

		1100
Office of	County of	renews 12-31-94
	hereby certify that the within instrument	
for record on the day of	UNION COUNTY	
(COUNTY OFFICIAL)	DEPU	·TY)
Form R6-7100-57 (9/71)	Date Received 11/3/24	*GPO591-971, 196