



NOTES:

Bearings are based on observation of the sun, SEE Book 1, pages 177-180 and 197-210, SEE Traverse Detail Sheet 2 of 2. All bearings and distances are true.

All field notes for traverses for Sections 26, 35, and 36 are in Book 1. Notes used to set Brass Caps are in Book 1, pages 211-215. All accessory ties for corners set in Sections 24, 35, and 36 are described in Certified Record of Land Monumentation.

Computations for all corners set are based on the manual of Surveying Instruction 1973, Chapter 5, SEE Book 1, page 216 for computations done.

The West and North line of Section 35 along with the North line of Section 36.

LEGAL DESCRIPTION

U.S. Forest Service ownership; all of section 25, all of section 26, and all of section 34. All being in Township 4 North, Range 39 East of the Willamette Meridian.

I, James H. Buisman, a registered land surveyor in the State of Oregon, hereby certify that this plat and the notes hereon or attached, are a correct representation of a survey I performed during April and May, 1980, for the U.S. Forest Service in accordance with the statutes of the State of Oregon and with the Articles of my contract.

James H. Buisman (S) James H. Buisman
Registered Land Surveyor
Oregon License No. 1097

- denotes Brass Cap set
- denotes Brass Cap found with bearing trees in good condition, set Barry Barbour, 1979
- () denotes GLO record bearings & distances, 1884
- denotes Forest Service Boundary

REGISTERED PROFESSIONAL LAND SURVEYOR
James H. Buisman
JAMES H. BUISMAN

| | |
|---|---|
| Sheet 1 of 2 | |
| KRUMBEIN ENGINEERING CO ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon | SCALE 1" = 500' DATE May 16, 1980 DRN BY MJ CKD BY J.H.B. DRNG NO 80-30C |
| Survey for U.S. FOREST SERVICE Sections 26, 35, & 36, T4N, R39E, W1M | |

31-80