calls from survey number 106-78 to reestablish the location of these intersections. The existing fenceline on the North and East fits the true line, but I find the fenceline on the South and West to be off the true line as shown. I also find a building encroachment on the South line of Lot 8 as shown. I find no other problems on this survey.

BASIS OF BEARING

The forward bearing as published by the U.S.C. and G.S. from △ College to △ Valley

REFERENCE MATERIAL

Plat of Riverside Addition 1922 Remonumentation of La Grande Survey Number 106-78

LEGEND

- Found brass tablet in water valve box set by survey number 106-78
- Position established by coordinate as per record calls of survey number 106-78 (monuments destroyed by current road
- Set 5/8"x 30" iron pin with plastic cap marked BGA SURVEY MARKER
- Record distance

 - Existing fenceline

REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman OREGON GREGORY T. BLACKMAN

VILLED FOLLS Data Rocaivad 9-14-83 Data Flad 9-28-83 EY GLANGLITZ DEPUTY Filo No. 34-83

BAGETT - GRIFFITH & ASSOCIATES La Grande, Oregon

> Map of Survey Parcels in Block 29, Riverside Addition to

La Grande UNION COUNTY, OREGON

SURVEYED FOR Jerry Ingerson 9/83 G.T.B. SURVEYED BY Drawn by: R.G.R. 9/83 Scale: 1"= 30"

 ∞