

SCALE FACTORS

Average Projection Scale 0.99989612485 Average Elevation Scale 0.99986331622 Average Combined Scale 0.99975945527

REFERENCE MATERIAL

Union County GPS Records Union County Monumentation Records GLO Contract Number 102 by Timothy W. Davenport dated July 20, 1863 GLO Contract Number 103 by David P. Thompson

dated September 3, 1863 Survey by J.W. Kimbrell dated April 8, 1887 recorded in the Old Book of Surveys on Page 7

Survey by J.W. Kimbrell dated September 5, 1888 recorded in the Old Book of Surveys on Page 91

Survey by J.W. Kimbrell dated September 8, 1888 recorded in the Old Book of Surveys on Page 94

ODOT Drawing Number 6B-19-1 ODOT Drawing Number 6B-19-2 Survey Number 25-92 Survey Number 051-1993 Survey Number 010-2001 Survey Number 034-2001 Survey Number 004-2002

LEGEND

Found OSHD Brass Disk- NGS Control Station "COVE", Union County GPS Point Number 9213

Found 5/8" pin with plastic cap marked "BGA SURVEY MARKER" as per Union County Monumentation records

Found Brass Cap monument as per Union County Monumentation records

Found 2 1/2" aluminum cap on 5/8" iron pin as per Union County Monumentation

Found 2 1/2" aluminum monument set by survey number 034-2001

Found 2 1/2" aluminum monument set by survey number 004-2002

Set 2 1/2"x30" aluminum monument

Set 2 1/2" brass cap on 5/8"x24" copper clad iron pin set in water valve box

Record information of GLO Contract Number 102

Record information of GLO Contract Number 103

Record information survey recorded on page 7 of the Old Book of Surveys

Record information survey recorded on page 91 of the Old Book of Surveys

Record information survey recorded on page 94 of the Old Book of Surveys

Record information survey number

Existing fence line

For monumentation information, see monumentation records filed separately.

For GPS Information sheet, see Union County Surveyor GPS book in Union County Surveyor Office, also filed with monumentation records.

NARRATIVE

This survey was performed as a part of an ongoing project to densify the monumentation and the GPS control network originally established by Eagle Survey Corporation in 1992. This area was severely lacking in monumentation. There were a few surveys executed in Sections 30 and 31 in the late 1800's by J.W. Kimbrell, then Union County Surveyor. The existing monumentation, and the existing fences within the section shown were located and search areas were established for the missing corners. Original corner evidence was severely lacking in this area. I do feel that the existing fences, particularly in the Southwesterly portion of this survey, do represent the positions of the original and Kimbrell surveys. I only monumented corners that I felt were in harmony with, and were a perpetuation of the original corner positions. This is not to say that the corners not monumented on this survey should not be searched for should a further sectional subdivision become necessary in the future. I do find a discrepancy in the corner dimensions along the West line of Sections 19 and 30. The two corners along the West side of the Southwest quarter of Section 19 were monumented by Harmon McLendon on survey number 004-2002. Mr. McLendon also based much of that survey on the existing fences and the state plane coordinates shown on ODOT drawing number 6B-19-1. The distances North and South of the Southwest corner of Section 19 appear to be shifted approximately 40 feet. Because of this discrepancy, I chose not to assign a GPS Number and information sheet to the corner to Sections 19, 30, 24 and 25. The bearings and distances are based on State Plane Coordinates NAD83(91). Elevations are NGVD 29 datum. I used GEOID 99 in determination of Ortho heights. I have prepared monumentation sheets and GPS Data sheets for the corners either observed statically, or monumented on this survey.



