

Township

Range

Union County, Oregon.

- The corner to Sec 7=8=17 1/8
 40 50 Set temporary fence North bet Sec 7 1/8
 40 50 Set temporary 1/4 Sec cor
 00 50 Set temporary cor. to Sec 5=6=7 1/8
 Hence North
 00 44 Intersect North Boundary 25 lbs East of cor to Sec 5=6=7 1/8
 Hence South
 00 02 Set Stone 6 x 8 x 30 inches for corner to Sec 5=6=7 1/8
 Hence South
 70 16 Set Post for 1/4 Sec cor bet Sec 7 1/8
 80 32 The cor to Sec 7=8=17 1/8
 The corner to Sec 4=5=8 1/4
 Hence West
 00 47 The corner to Sec 5=6=7 1/8 Hence West
 40 00 Set temporary 1/4 Sec cor
 80 75 The corner to Sec 6=7=17 1/2 Hence East
 40 04 Set Stone 6 x 7 x 18 inches for 1/4 Sec cor bet Sec 6 1/2
 Hence South through Sec 7
 40 00 Set temporary center Sec 7
 00 00 Set temporary 1/16 cor
 80 22 The 1/4 Sec cor bet Sec 7 1/8
 Hence North
 20 06 Set Stone 6 x 5 x 20 inches for 1/16 cor
 40 11 The center
 The 1/4 Sec cor bet Sec 7 1/2
 Hence East through Sec 7
 09 89 The center Sec 7
 74 89 The 1/4 Sec cor bet Sec 7 1/8
 Hence West
 40 18 Set Stone 6 x 12 x 20 inches for center Sec 7
 J. K. Smith & Sons Co Surveyors