

Township 6 South

Range 38 East

Union County, Oregon.

CHAINS. LRS.

- Thence South through Sec. 11
- 40 33 Set Post for center Sec 11
from which
a Pine 10 inch dia tree S 22 1/2° W 192 lks dist
- 60 38 The center S 1/2 Sec 11
Thence West through SW 1/4 Sec 11
- 40 46 The 1/8 corner on West Boundary SW 1/4 Sec 11
Thence East through center SW 1/4 Sec 11
var. 20° E
- 20 23 Set Post for 1/16 corner in center SW 1/4 Sec 11
- The Corner to Sec 10 = 11 = 14 & 15
Thence East bet Sec 11 & 14
var 20° E
- 40 26 The 1/4 Sec corner bet Sec 11 & 14
Thence East bet Sec 11 & 14
var 40° E
- 20 00 Set Temporary 1/8 corner
- 37 50 The corner to Sec 11 = 12 = 13 & 14
Thence West bet Sec 11 & 14
- 18 75 Set Post for 1/8 corner
Thence North through SE 1/4 Sec 11
- 20 00 Set Temporary 1/16 corner
- 39 75 Intersect 1/16 corner in center E 1/2 Sec 11
Thence South through center SE 1/4
- 19 87 1/2 Set Post for 1/16 corner in center SE 1/4 Sec 11
- 39 75 The 1/8 corner on South Boundary SE 1/4 Sec 11

J. W. Kimball County Surveyor