

Township 3 South

Range 40 East W. M.

Union County, Oregon.

CHAINS.	LKS.	
		George Thomas Jun 18. 1899
		I commenced at the
		South West Corner
		of Section 14 Then
		North Var. 21° 30'
20		Set Temporary Stake
40		" " 1/4 Sec. Cor.
50		" " Stake
60		" " "
80		" " Cor. to sec.
		11-14-10-15 Then North
121	16	To the 1/4 Sec. Cor. Then South
40	40	Set Section Cor on East and West line a marked stone 16-8-6 inches
		Then South
20	20	Set 1/8 Sec. Cor. w. stone 16-12-6 inches
30	30	" a stake
40	40	Set the 1/4 Sec. Cor. a stone 16-14-6 inches
60	60	" " 1/8 " " "

Arthur Curtis
County Surveyor