Sheet 1 of 3 Microfilm Number 202/2804 PARTITION PLAT NUMBER 2021-0017 Plat Cabinet Number E544,545, 546 2 1/2" aluminum C-W 1/16

Partition Plat

COMMONDET

CARCEL 1

CARTITION S A partition of Parcel 2 of Partition Plat 1996-09 and other lands situated in the Northeast quarter of the Southwest quarter of Section 17, Township 3 South, Range 38 East of the Willamette Meridian, Union County, Oregon ② Δ=68°29'00" $\triangle = 50^{\circ}27'01''$ Δ=50°27'01" Forward bearing as published by the U.S.C. Δ=30°58'27' 6 Δ=27°00′55″ $(5) \Delta = 27^{\circ}00'55''$ N89°41'36"W 210.15 R=135.00'and G.S. from \triangle COLLEGE to \triangle VALLEY R = 75.00'R=130.00'R = 70.00'R = 70.00'R=130.00'<N89°35'27"W> <210.33> L=72.98'Dated 1946. L=89.64' L=114.47' L=61.64'L=33.01L=61.30'/227±/ /N90°00'00"E/ L.C.=72.10'L.C.=84.40' L.C.=110.81 L.C.=59.66'L.C.=32.70'L.C.=60.73'SCALE: 1"=100' Building on Parcel 1 -N15°29'11"E N3475'41"E N84°01'11"W S84°01'11"E N8475'46"E S84°15'46"W P2004006T falls South of line 6.0 ft. LEGEND Δ=22°30′19″ <u>β</u> Δ=8°45'38' (11) Δ=97°40'04" (9) Δ=97°02'08" (10) Δ=1973'17' <u>12</u> Δ=31°19'12" 13 Δ=45°26'31" R=273.08'R=273.08'R=333.08'R=183.16' R=60.00'R=60.00'R=45.00'L=107.26'L=41.75'L=145.27' Found monument as described, morked as per Union L=101.62'L=20.13'L=76.71'L=182.07' /768.94/ **774.08** \odot County Monumentation records L.C.=106.57L.C.=41.71L.C.=89.90' L.C.=20.03'L.C.=67.75' L.C.=179.81' L.C.=141.49' N36°25'30"E N52°03'28"E N6810'09"E S10°02'27"W S89°55'40"E N40°46'41"E N41¶4'18"E Found 5/8" iron pin set by Survey Number 6-73/Δ=18°35'17"/ /Δ=97°40'04"/ 1318.12 /R=60.00'/ /R=45.00'/ **318.80** /315.28/ {315.28} /L=19.47'/ Found 5/8" iron pin set by Survey Number 30-90 /L=76.71'/ POINT OF /T=9.82'/ /T=51.46°/ BEGINNING PLAT Found 5/8" iron pin with plastic cap marked BGA /N89°43'36"E/ -S88*36'E-Found pin disturbed. SURVEY MARKER, set by Partition Plat 1993-011 [N89'48'05"E] /164.93/ \$89'48'05"W 164.02 -394.26-[S88°09'12"E] Searched for, not approx 0.4 ft East of [392.25] **392.47** found. Held record N88'09'12"W true corner position /S89°43'36"W/ Found 5/8" iron pin with plastic cap marked APA, set angle. 217.20 /223.24/ by Partition Plat 1996–09 Found 5/8" iron pin with plastic cap marked AP&A, /Δ=68°29'00"/ set by Survey Number 007-1992 [N89°52'55"E] /R = 75.00'//L=89.64'/ [128.32] **210.63** /210.32/ /T=51.05'/ Found 5/8" iron pin with plastic cap marked BGB 128.32 SURVEY MARKER, set by Survey Number 038-1995 - **181.02** –180.95– /94.26/ PARCEL 1 PARTITION PLAT ~S89*52'55"W 275.28 PARCEL 3 Found 5/8" iron pin set by Survey Number 26-75 PARCEL 2 2.04 acres Found 5/8" iron pin with plastic cap marked BGB SURVEY MARKER, set by Partition Plat 20040006T N3574'43"E 5.91 | SEE DETAIL PG 2 9.34 acres Set 5/8"x30" iron pin with plastic cap marked BGB Found pin North 0.5 ft. /Np.09'04"W/ SQ*11'29"W SURVÉY MARKER _and West 1.0 ft. from S8273'46"E (5) true corner position Centerline N3574'43"E 11.51 Easement Line _N16°52'40"E N14°38'04"E MF 36287 47.63 16.86 Record measurement as per Survey Number 6-73 Found witness pin N89°31'45"E, 1.06 ft. PARCEL 1 Record measurement as per Survey Number 30-90 -N89°53'15"W-(N89°51'12"W) **N89°31'45"E** Record measurement as per Survey Number 038-1995 Record measurement as per Partition Plat 1993-011 69.58 Found pin buried South Record measurement as per Partition Plat 1996-09 1.7 feet and West 1.8 feet of corner position. SURVEY NUMBER /85±/ ossibly disturbed. Record measurement as per Partition Plat 20040006T NARRATIVE EAST 235.94 Portion to be dedicated by # Braden's This partition was done at the request of Tom Geraci, owner of the land within. Mr Geraci wanted to divide the land as shown. I recover the monuments as shown. The monuments on the South line of the Braden Tract are harmonious with Survey 30-90. Finding no remaining monuments along the West line of this tract, I hold the record angle and distance from the pins on the South line to place the NW corner (on the West line) of the Braden Tract, in the center of Lakeview Drive. To place the common line between Braden's and Geraci's, I run record bearing and distance Northeasterly, to the pin at the where the North line of the Braden Tract meets the East line of Lakeview Drive, rotated to my basis of bearing. As the Geraci property line runs Southwest of the Braden tract, I hold record *INDEX* (N41 18'27"W) S41'00'05"E measurements as per Partition Plat 1996-09. I find this relatively harmonious with the pin PAGE 1 - Partition Plat, Legend, set by Survey Number 038-1995 on the West edge of the cul-de-sac. I take any error BRADEN (7.77) **7.7**7 Narrative out in the last course along the West edge of the cul-de-sac. Establishing the irregular line in this manner maintains harmony of the record dimensions of the plat in the best PAGE 2 - Details, Reference possible manner. Materials, Easements As the line continues to the West, I hold the pins set by Survey Number 038-1995. PAGE 3 — Approvals, Declaration, The last course, I hold the pin set by Survey Number 007-1992 and extend it to the Surveyor's Certificate aliauot line. Along the North line of this property, I find pins set by Survey 6-73 harmonious with 2" aluminum cap, set by Survey Number record measurements of surveys along this line. The exception is at the 90° angle point REGISTERED on the Eastern portion of the North line, where I find this monument disturbed. I hold the PROFESSIONAL bearing of the line of the monuments to the East and intersect with a line, held at record SURVEYOR'S EXACT COPY STATEMENT LAND SURVEYOR N89'40'26"W 313.83 angle, from the pin 92 feet to the South. At the angle point on the North line where I Survey Number 024-2000 {N89°53'15"W} {313.83} can find no remains of the original monument, I hold record angle as per Partition Plat I, Jeffrey S. Hsu, registered Oregon Surveyor No. 83571, do hereby certify 1993-011. that I am the Surveyor who prepared the Partition Plat No. 262 HO17 and that the OREGON JUNE 2, 2010 I place the partition lines and the dedicated road at the direction of Mr. Geraci. annexed tracing is an exact copy of said Partition Plat as the same is on file in Since the constructed road does not follow its intended easement as it borders the Braden JEFFREY S. HSU UNION COUNTY Cabinet Number **E544.545.546** of the Plat Records of UNION COUNTY, and Larvik property, they have both participated in this dedication to correct this. 83571 I find no other unusual conditions with this partition. and said exact copy is submitted as per O.R.S. 92.120. Renewal Date: June 30, 2021 Sheet 1 of 3

Jeffrey S. Hsu. OPLS 83571

Microfilm Number 202/2804 Plat Cabinet Number ES44, ES45, ES44

A partition of Parcel 2 of Partition Plat 1996-09 and other lands situated in the Northeast quarter of the Southwest quarter of Section 17, Township 3 South, Range 38 East of the Willamette Meridian, Union County, Oregon

SURVEYOR'S CERTIFICATE

I, Jeffrey S. Hsu, Registered Professional Land Surveyor, hereby certify that I have surveyed and platted the land within this partition, being a partition of Parcel 2 of partition Plat No. 1996—09 and other land situated in the Northeast quarter of the Southwest quarter of Section 17, Township 3 South, Range 38 East of the Willamette Meridian, Union County, Oregon, more particularly described as

Beginning at the Northeast corner of Parcel 2 of Partition Plat 1996-09, filed as Microfilm Number 961983 and stored in Slide 426, Plat Cabinet 'B', plat records of Union County, Oregon,

Thence: South 89°48'05" West, along the North line of said Parcel 2, a distance of 164.02 feet,

Thence: South 0°07'05" East, along the exterior of said Parcel 2, a distance of 92.76 feet, to an angle point in said exterior,

Thence: South 89°52'55" West, along said exterior, a distance of 275.28 feet, to an angle point in

Thence: North 2°58'05" West, along said exterior, a distance of 88.93 feet, to an angle point in said

Thence: North 88°09'12" West, along said exterior, a distance of 392.47 feet, to an angle point in said exterior,

Thence: North 0°07'54" East, along said exterior, a distance of 318.80 feet, to the South line of Parcel 1 of Partition Plat 20040006T,

Thence: North 89°41'36" West, along said South line, a distance of 210.15 feet, to the West line of the Northeast quarter of the Southwest quarter of said Section 17,

Thence: South 0~11'29" West, along said West line, a distance of 774.08 feet, to the South line of said Parcel 2 of Partition Plat 1996-09.

Thence: Along the South line of said Parcel 2, the following 7 courses

North 89°31'45" East, a distance of 69.58 feet,

South 37'37'09" East, a distance of 155.51 feet,

South 50°22'29" East, a distance of 53.35 feet, South 66°31'31" East, a distance of 86.36 feet,

South 59°30'14" East, a distance of 120.70 feet,

South 69°22'06" East, a distance of 129.68 feet,

South 41°00'05" East, a distance of 7.77 feet, to a point on a 60.00-ft. radius non-tangent curve to the left,

Thence: Along said curve, a distance of 20.13 feet, through a central angle of 1973'17" (the long chord which bears South 10°02'27" West, a distance of 20.03 feet),

Thence: South 41°05'38" East, a distance of 39.69 feet, to the PC of a 45.00-ft. radius curve to

Thence: Along said curve, a distance of 76.71 feet, through a central angle of 97°40'04" (the long chord which bears South 89°55'40" East, a distance of 67.75 feet), to a point on a 183.16-ft. non-tangent curve to the left.

Thence: Along said curve, a distance of 145.27 feet, through a central angle of 45°26'31" (the long chord which bears North 41"14'18" East, a distance of 141.49 feet),

Thence: North 4911'19" East, a distance of 73.44 feet,

Thence: North 56°26'17" East, a distance of 47.11 feet, to the PC of a 333.08-ft. radius curve to

Thence: Along said curve, a distance of 182.07 feet, through a central angle of 3119'12" (the long chord which bears North 40°46'41" East, a distance of 179.81 feet),

Thence: North 24°35'51" East, a distance of 157.67 feet,

Thence: North 16°52'40" East, a distance of 47.63 feet,

Thence: North 3514'43" East, a distance of 11.51 feet,

Thence: North 35°14'43" East, a distance of 5.91 feet,

Thence: North 0°03'36" West, a distance of 210.63 feet, to the PC of a 75.00-ft. radius curve to

Thence: Along said curve, a distance of 89.64 feet, through a central angle of 68°29'00" (the long chord which bears North 34°15'41" East, a distance of 84.40 feet) to the Point of Beginning.

Containing 15.27 acres
I further certify that I made this plat by order of and under the direction of the owner thereof, and that boundary and parcel corners are marked with monuments as indicated on the annexed plat, in accordance with O.R.S. 92.050 and 92.060.

Jeffrey S. Hsu, OPLS 83571 Bagett, Griffith and Blackman 2006 Adams Avenue LaGrande, OR 97850

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

DECLARATION/DEDICATION

Know all People by these presents that THOMAS K. GERACI is the owner of the land within this Partition, being more particularly described in the accompanying Surveyor's Certificate, and has caused the same to be surveyed and platted as shown on the annexed map, and does hereby dedicate, donate, and convey for public use forever the land within LAKEVIEW DRIVE, all in accordance with O.R.S.

Know all People by these presents that LANDON L. BRADEN and VANESSA R. BRADEN, are the owners of a portion of the land within LAKEVIEW DRIVE of this Partition, and have caused the same to be surveyed and platted as shown on the annexed map, and do hereby dedicate, donate, and convey for public use forever the land within LAKEVIEW DRIVE, all in accordance with O.R.S. Chapter 92.

Know all People by these presents that CORY LARVIK and HEATHER LARVIK, Trustees of the Larvik Family Trust dated November 2, 2017, are the owner of a portion of the land within LAKEVIEW DRIVE of this Partition, and have caused the same to be surveyed and platted as shown on the annexed map, and do hereby dedicate, donate, and convey for public use forever the land within LAKEVIEW DRIVE, all in accordance with O.R.S. Chapter 92..

ACKNOWLEDGMENT

State of Oregon County of Union

Know all people by these presents, on this day of June, 2021. before me a Notary Public in and for said State and County, personally appeared THOMAS K. GERACI, who is known to me to be the identical person named in the foregoing instrument, and who being duly sworn, did say that they executed the same freely and with tarily.

OFFICIAL STAMP

Notary Public for the State of Oregon

OFFICIAL STAMP
EMMITT CHARLES AMBERT NOTARY PUBLIC - OREGON MY COMMISSION EXPIRES MARCH 15, 2025

Notarial seal

State of Oregon

County of Union

Know all people by these presents, on this day of Jove, 2021. before me a Notary Public in and for said State and County, personally appeared LANDON L. BRADEN and VANESSA R. BRADEN, who are known to me to be the identical persons named in the foregoing instrument, and who being duly sworn, did say that they executed the same freely

and voluntarily. many there es A vilze Notary Public for the State of Oregon

OFFICIAL STAMP **EMMITT CHARLES AMBERT NOTARY PUBLIC - OREGON COMMISSION NO. 1010101** MY COMMISSION EXPIRES MARCH 15, 2025

Notarial seal

State of Oregon County of Union

Know all people by these presents, on this 9th day of une, 2021. before me a Notary Public in and for said State and County, personally appeared CORY LARVIK and HEATHER LARVIK, who are known to me to be the identical persons named in the foregoing instrument, and who being duly sworn, did say that they executed the same freely and

the State of Oregon

Tomas Benitez III NOTARY PUBLIC - OREGON COMMISSION NO. 1007575 MY COMMISSION EXPIRES Januray 12, 2025

APPROVALS

Union County Surveyor

Approved this 5 to day of June, 2021.

By Grant County Surveyor

Union County Planning Commission

Approved this IH day of Soly , 2021.

Union County Planning Director

Union County Assessor / Tax Collector

I hereby certify that pursuant to O.R.S. 92.095, all ad valorem taxes and all special assessments, fees and other charges required by law to be placed upon the 2028 2027 tax roll which became a lien on the land within this partition or will become a lien during the tax year but not certified to the tax collector for collection have been paid.

Cody Vavra, Union County Assessor/Tax Collector

Union County Commissioners

Approved this 2l day of

FILING STATEMENT Union County Clerk

State of Oregon SS County of Union

I do hereby certify that the attached partition plat was received for record on this 2/57 day of July , 2021, at 10:13 o'clock A.M., and recorded in Plat Cabinet No. ES44, ES45, E546 Union County records. Microfilm Number 202/2804

Robin A. Church Union County Clerk

by Helen Tucker, Deputy Clark

SURVEYOR'S EXACT COPY STATEMENT

I. Jeffrey S. Hsu, registered Oregon Surveyor No. 83571, do hereby certify that I am the Surveyor who prepared the Partition Plat No. 2021-0017 and that the annexed tracing is an exact copy of said Partition Plat as the same is on file in UNION COUNTY Cabinet Number ES44,545,546 the Plat Records of UNION COUNTY, and said exact copy is submitted as per O.R.S. 92.120.

Jeffrey S. Hsu, OPLS 83571

Sheet 3 of 3