


CORNER REFERENCE INDEX

EXAMPLE

REFERENCE NO.	EXPLANATION
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

└── year filed
 └── file no.



REFERENCE NO.	NOTES & DESCRIPTION
SURVEY # 156	STONE IN PLACE ? - 1948
SURVEY # 158	STONE ? - 1951
SURVEY # 159	STONE ? - 1952
SURVEY # 43-73	CONC. MON. VOELZ - 1973
SURVEY # 44-74	FOUND IRON PIN SET IN CONCRETE ANDERSON - 1974
SURVEY # 5-76	FOUND MONUMENT OF RECORD GRIFFITH - 1976
SURVEY # 31-77	BRAZEAL - 1977
SURVEY # 32-78	FOUND 1" IRON PIN HAMBLETON - 1978
SURVEY # 21-79	FOUND MONUMENT OF RECORD GRIFFITH - 1979
SURVEY # 4-82	FOUND IRON PIN IN CONCRETE BLACKMAN - 1982
SURVEY # 2-86	CORNER FOUND?, BT WAS GONE NEAL - 1917
SURVEY # 9-86	FD. 1" PIN IN CONCRETE PER SURVEY # 2-74 BLACKMAN - 1986
SURVEY # 17-86	FD. 1" PIN IN CONCRETE PER SURVEY 2-74 GRIFFITH - 1986
SURVEY # 18-86	SET 2 1/2" X 30" ALUMINUM MONUMENT FROM TIE TO HINDMAN'S ADD.
	AND SURVEY # 103, FOUND 1" IRON BAR BEARING S 61° 58' 09" W.
	31.62 FEET FROM ALUMINUM MONUMENT. SUTTON - 1986
81-86R	MONUMENTATION RECORD SUTTON - 1986
84-86R	MONUMENTATION RECORD BLACKMAN - 1986
SURVEY 028-1998	FD 1" PIN IN CONCRETE ROBINSON - 1998
SURVEY 007-1999	FOUND 1" PIN ROBINSON - 1999
SURVEY 001-2001	FOUND 1" PIN IN CONCRETE BLACKMAN - 2001
GPS # 200106	GPS OBSERVATION BLACKMAN - 2001
SURVEY 012-2003	FOUND 1" BENT ROD STRATTON - 2003
SURVEY 014-2007	FOUND 1" IRON ROD POSADA - 2007
SURVEY 011-2010	FOUND 1" IRON PIN DISTURBED ROBINSON - 2010
019-2010R	MONUMENTATION RECORD ROBINSON - 2010
SURVEY 020-2015	FOUND 2 1/2" ALUMINUM MONUMENT HSU - 2015
SURVEY 027-2018	FOUND 2 1/2" ALUMINUM MONUMENT HSU - 2018
SURVEY 012-2020	FOUND 3" ALUM. CAP ILLEGIBLE ELITHORP - 2020
SURVEY 002-2023	FOUND 2 1/2" ALUMINUM MONUMENT HSU - 2023

CORNER LOCATION CODE N15