
## CORNER REFERENCE INDEX

## REFERENCE NO. IO-83 Refer to Survey Map File IO-83N Refer to Narrative File IO-83R Refer to Corner Restoration File year filed

— file no.



REFERENCE NO.	NOTES & DESCRIPTION	· ·
Survey # 36-72	3" PIPE FILLED WITH CONC. (17.68'S OF GR) VOELZ-	1972
		microscope de la companya del companya de la companya del companya de la companya
		google-ve-commenseering/date
		VIII.
		OF THE PARTY OF TH
		Manusconer and deficiency
		and the second of the second o
		property water and definition to
		Name and Associated Association (Associated Association (Associated Association (Associated Association (Associated Association (Association (Associ
		***************************************
		Managaran (1997) And State (1997)
		MCDAY TEXAS AND
		***************************************
		CORNER —
		Z
Appropriate and an internal control (CA) (in couple on an amount about the couple of an amount activation of the appropriate activation of the couple of the		\biggreen \
		0
		LOCATION
		င
		CODE
		=
Separation of the second secon		
		ľ
		Manufacture de la constantina del constantina de la constantina del constantina de la constantina de l