


CORNER REFERENCE INDEX

EXAMPLE



REFERENCE NO.	EXPLANATION
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

└── year filed
 └── file no.

REFERENCE NO.	NOTES & DESCRIPTION
SURVEY # 5-80	POSITION DETERMINED BY STATE HIGHWAY TIES BLACKMAN-1980
SURVEY # 21-83	POSITION DETERMINED BY STATE HIGHWAY TIES BLACKMAN-1983
SURVEY # 10-84	POSITION FROM STATE HIGHWAY TIES BLACKMAN-1984
SURVEY # 13-86	POSITION ONLY FROM STATE HIGHWAY TIES - EASTERN RIGHT-OF-WAY MONUMENT. UNION COUNTY SUPERVISOR -1986
67-88 R	MONUMENTATION RECORD BLACKMAN-1988
SURVEY 44-88	FD. 5/8" IRON ROD PER MONUMENTATION RECORDS BLACKMAN-1988
SURVEY 29-89	FD. 5/8" IRON PIN PER MON RECORDS ROBINSON-1989
SURVEY 044-1995	Found 5/8" pin per mon Record ROBINSON-1995
SURVEY 008-1996	FND 5/8" PIN w/ PLASTIC CAP ROBINSON-1996
SURVEY 018-1996	FND 5/8" PIN w/ PLASTIC CAP ROBINSON-1996
SURVEY 036-1996	FND 5/8" I.R. w/ YELLOW PLASTIC CAP BRINTON-1996
SURVEY 021-1999	FND 5/8" IRON PIN w/ PLASTIC CAP ROBINSON-1999
SURVEY 022-1999	FND 5/8" IRON PIN w/ PLASTIC CAP ROBINSON-1999
GPS #9211	GPS OBSERVATION (ATTACHED) CASWELL-1992
SURVEY 010-2001	FND 5/8" IRON PIN BLACKMAN-2001
SURVEY 024-2001	FND 5/8" IRON PIN ROBINSON-2001
SURVEY 019-2009	FND 5/8" IRON PIN ROBINSON-2009
5150-2015R	MONUMENT RECORD - REPLACED MONUMENT ELITHORP-2015
SURVEY 048-2021	FND 1 1/2" ALUMINUM CAP WHEELER 2021
SURVEY 035-2022	FND 2 1/2" ALUMINUM CAP HSU-2022