

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**


**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner originally established by John W. Kimbrell under GLO contract Number 579, dated June 22, 1891. Surveyor General record states:

Set a post for the 1/4 corner of sections 20 and 21 from which:

A Fir 6 inches in diameter, bears N 25° E, 96 lks.

A Fir 10 inches in diameter, bears S 36-1/2° W, 63 lks.



**DIAGRAM**

No record of subsequent monumentation found in Union County survey records.

**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Found old fence lines north-south and east.

See narrative on Map of Survey No. 034-1994 for corner position selection.

See Map of Survey No. 034-1994

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position as determined, (narrative on survey 034-1994), I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 27 inches in the ground, from which;

**NEW BEARING TREES:**

A 16 inch diameter White Fir bears N 64° E, 48.40 feet marked 1/4 S21 BT

A 8 inch diameter Tamarack bears S 29° E, 33.37 feet marked X BT


A 22 inch diameter Tamarack bears S 61°W, 122.64 feet marked 1/4 S20 BT

A 11 inch diameter White Fir bears N 45° W, 42.75 feet marked 1/4 S20 BT

Painted a 6" red band around all BTs and attached Bearing Tree signs.

Set a steel fence post approximately 2 feet North with a Land Survey Monument sign attached.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>7/26/94</u>
Date Filed	<u>8/23/94</u>
By	<u><i>Hugh T. Black</i></u>
File No.	<u>030-1994R</u>



I hereby certify that the above corner point was perpetuated as hereon described on July 13, 1994.  
Witnesses: Pete Crabtree.

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*Duane I. Griffith*

OFFICER  
JULY 10, 1984  
**DUANE I. GRIFFITH**  
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.