CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None

| T1N R39E J-12 | | | |
|---------------|-----|----|--|
| | Sec | 16 | |
| | | | |
| DIAGRAM | | | |

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Minor Partition 1994-01

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Midway and on line between the North $\frac{1}{4}$ corner and the Northeast section corner of section 16 I set a 5/8" x 30" iron pin (rebar) with 2" aluminum cap marked as shown below, 30" in the ground, from which;

A $5/8" \times 30"$ iron pin (rebar) bears $$85^{\circ}20'46"E$, 236.94 feet with plastic cap marked "BGA SURVEY MARKER".

A $5/8" \times 30"$ iron pin (rebar) bears 50°54'05"W, 255.46 feet with plastic cap marked "BGA SURVEY MARKER".

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JEFFERY P. PETERSEN 2625 JULY 20, 1993

P. Peterson

T1N R39E

S9 E 1/16———— S16

> 1993 OPLS 2625

I hereby certify that the above corner point was perpetuated as hereon described on November 23, 1993. Witness: Mike Schlegel.

1-24-94 1-24-94 1-24-94 1-24-94 001-1994 R

Accessory bearing and distance determined by Minor Partition 1994-01.

J-12 5912