## UNION COUNTY SURVEYOR

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.


No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 033-2004 Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 5/8" x 30" iron pin with 2 ½" aluminum cap, marked as shown, 26 inches in the ground from which:

## T1N R39E P-12



## NEW BEARING OBJECTS:

A 5/8 inch iron pin with 2 inch aluminum cap marked "BGB SURVEY MARKER SW RP" bears S  $50^{\circ}43'$  W, a distance of 19.04 feet.

A 5/8 inch iron pin with 2 inch aluminum cap marked "BGB SURVEY MARKER NW RP" bears N 44°28' W, a distance of 25.07 feet.

Set steel fence post approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on October 13, 2004.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON 2219

Renewal Date December 31, 2004

E 1/16

C S 21

2004

OPLS 2219

UNION COUNTY SURVEYOR

Date Received

Date Filed

Filed By

File Number 053 - 2004 le

I used Leica GPS System 530 in the establishment of the new bearing objects. The basis of bearing is that of survey number 033-2004. Distances are to the center of the bearing objects.