CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT: None

No record of subsequent monumentation found in Union County survey records

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Union County Survey Number 043-1995.



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

At the position determined by the survey I set a 2½"x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which;

NEW BEARING TREES:

A 9" Tamarack bears S40°W, 65.59 feet, marked CE 1/16 S6 BT. A 11" Tamarack bears N70°W, 98.41 feet, marked X BT.

I hereby certify that the corner was monumented on October 13, 1995. Witness: Mark Durbin, Jeff Madsen

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JEFFERY P. PETERSEN

eterse

2625 Renewal Date: December, 31 1996

T2S R36E E 1/18 86 1995 2625 **OPLS**

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree.

UNION COUNTY **SURVEYOR** Date Received 11-13-95 Date Filed 11-13-95 1995 R File Number 035

CEI FIED RECORD OF LAND CORNER MONUMENTAL N

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Jeffrey Petersen in Survey Number 043-1995. Monumentation record 035-1995R states:

At position determined by survey, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

A 9" Tamarack bears S40°W, 65.59 feet, marked CE 1/16 S6 BT. A 11" Tamarack bears N70°W, 98.41 feet, marked X BT.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner set by Petersen was based on an erroneous position of the NW corner of Section 6. From true corner position:

A 2 ½" Aluminum pipe bears East, 3.80 feet, with cap marked as shown. A 12 inch Western Larch bears South 38° West, a distance of 63.16 feet, with scribe marks CE 1/16 S6 BT on a partially healed blaze.

A 15 inch Western Larch bears North 66° West, a distance of 94.75 feet, with a healed blaze.

See Survey Number 016-2011.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At position determined by survey, I set a 5/8" x 30" iron pin with 2 ½" Aluminum cap, marked as shown below.

I remove the cap off the original aluminum pipe monument and amend the information on the bearing tree tags. Corner falls on the South side of the Interstate Highway on a Northeast facing slope.

I hereby certify that the corner was monumented on June 1, 2011. Witness: Gregory T. Blackman Jr.



Renewal Date: June 30, 2011



UNION COUNTY
SURVEYOR

Date Received 4/23/11

Filed By 6 COBG SON, DERTY

File Number 009 -2011 R

I used a magnetic compass and steel tape in the establishment of the accessories. Magnetic declination used was 16° East. The distances are to a spike in the right hand side of the trees and bearings are to a brass washer to the center of the BT blaze.

S 6

