#### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### History of original corner establishment:

In July 1882, under GLO Contract No. 450, Henry Meldrum set a post 4 ft. long, 4 ins. square 24in. in ground for Cor. to Secs. 9, 10, 15 & 16 marked T2S S10 on N.E.

R40E S9 on N.W. S16 on S.W. and S15 on S.E. with

4 notches on South and 3 on East edges, from which:

A Fir 6 ins. dia. bears S28°W 32 lks. dist. marked S16 BT A Fir 9 ins. dia. bears S22°E 86 lks. dist. marked S15 BT

A Fir 4 ins. dia. bears N73°E 47 lks dist. marked T2S S10 BT

A Fir 20 ins. dia. bears N18°W 50 lks dist. marked R40E S9 BT

Index Fil	le No. J-13			
DIAGRAM				
	R40E			
<u>\$9</u>	S10			
\$16	S15			
	•			

T2S

**S9** 

**S16** 

R40E

**S10** 

S15

1981

OR PLS 1294

### Description of corner evidence found:

A diligent search was made and could find no evidence of original post or original BT's.

# Description of monument and accessories I established to perpetuate the original location of this corner:

Therefore at double-proportioned position from corners found two miles north, and one mile east, south and west; set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 18" in ground to solid rock with mound of stone to cap.

Bearing Trees:

A Tamarack 12" dia. bears N14° E, 22.5 ft. scribed

T2S R40E S10 BT

A Tamarack 14" dia. bears S55° E, 14.8 ft. scribed

T2S R40E S 15 BT

A Tamarack 11" dia. bears S85°W, 32.1 ft. scribed

T2S R40E S16 BT

A Tamarack 10" dia. bears N43°W, 49.9 ft. scribed

T2S R40E S9 BT

Attached 54-3 & 54-4 signs to all BT's and brass washer stamped LS 1294 to foot blaze of all BT's. Painted blazes and 6" band around all BT's red.

Attached 54-4 sign to metal post 5' north of corner.

I hereby certify the above corner monument was reestablished as herein described on September 11, 1981.

> Witnesses: R. Orton

G. Orton

(DEPUTY)

Office of County Surveyor Union State of...Oregon ..... , I hereby certify that the within instrument was filed in this office 19.81 for record on the .. 26... day of .... October Howard L. Perry (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

HOWARD L

BUCHSTEPED PROFESSIONAL

YOR

ារមេ	Keceived
	☆ GPO-798-276
Date	Filed

File No. 337-84 R

By

# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

· History of original corner establishment:

Refer to Union County Remonumentation Record No. 337-84R and Union County Survey No. 74-81 for original corner information and for 1981 establishment of corner position.

DIAGRAN	1
T2S	R40E
9 16	10

#### Description of corner evidence found:

Found the 1981 monument as previously described.

Refer to survey recorded during September, 1989 which revises Survey 74-81.

Description of monument and accessories I established to perpetuate the original location of this corner:

## FROM WHICH:

The 1981 NE BT, a 12" Western Larch, alive and in good condition, marked as pre-viously described, bears N 28° E 10.7 feet.

The 1981 SE BT, a 14" Western Larch, alive and in good condition, marked as pre-viously described, bears S 27° E 23.8 feet.

The 1981 SW BT, an 11" Western Larch, alive and in good condition, marked as previously described, bears S  $66^\circ$  W 35.1 feet.

The 1981 NW BT, a 10" Western Larch, alive and in good condition, marked as previously described, bears N 54° W 42.0 feet.

Magnetic compass (18-1/2° E. Declination). Steel Tape.

September 6, 1989

I hereby certify that the survey activities described on this record were performed under my direct supervision.

Gary L. Langlitz, LS 1099 David Siderius

REGISTERED PROFESSIONAL LAND SURVEYOR	
Chuld In	_
OREGON SEPTEMBER 23, 1977 HOWARD L. PERRY 1 2 9 4	

Reset 1989 OR PLS 1294

Office of			
(COUNTY OFFICIAL)	(DEPUTY)		
Form R6-7100-57 (9/71)		Date Received 9-18-89 # GPO 799-509 Date Filed 9-18-89	
		By G. LANGLINZ	