HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 39 E Y-20

S 35

DESCRIPTION OF CORNER EVIDENCE FOUND: None.

SEE SURVEY NUMBER 018-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin, 26" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:


NEW BEARING OBJECTS:


A 5/8"x30" iron pin bears North 42°21' East, a distance of 13.86 feet, with 1 $\frac{1}{2}$ " aluminum cap marked N RP. A 5/8"x30" iron pin bears South 19°30' East, a distance of 13.90 feet, with 1 $\frac{1}{2}$ " aluminum cap marked S RP.

Set a steel fencepost approx. 0.5 ft. North of monument. I hereby certify that the corner was monumented on May 29, 2020. Witness: Kyle A. Tucker



Renewal Date: June 30, 2021





I used a Leica GS-18 RTK GPS in the establishment of the accessories. Basis of bearings is as per Survey Number 018-2020.