
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by David P. Thompson under GLO contract number 103 dated September 3rd, 1863. Surveyor General field notes state:

Set post for 1/4 Sec. corner in mound of earth with pits, trench, charred stake as per instructions.

Union County Survey Record 043-84 dated September 19, 1984 by Norman Paullus, OPLS 1952, shows a proportioned position.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None. The painted center line intersection of Gekeler Lane and Buchanan Lane falls 2.9 feet North of the proportioned position.

SEE SURVEY NUMBER 004-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportionate position I set a 5/8" x 30" iron pin, 30 1/4" in the ground with 2" brass cap marked as shown below, cemented in a 4" hole cut in the asphalt road surface, from which:

A 5/8" x 30" iron pin bears North 41°26' East a dist. of 45.77 ft., with 1 $\frac{1}{2}$ " aluminum cap

marked NE RP. A $5/8" \times 30"$ iron pin bears South $47^{\circ}59'$ East a dist. of 31.75 ft., with 1 ½" aluminum cap marked SE RP.

A 5/8" imes 30" iron pin bears South 57°11' East a dist. of 28.04 ft., with 1 imes" aluminum cap marked SW RP.

marked NW RP.

I hereby certify that the corner was monumented on March 27, 2019. Witness: Kyle A. Tucker

REGISTERED **PROFESSIONAL** LAND SURVEYOR

JEFFREY S. HSU 83571

OREGON

Renewal Date: June 30, 2019

GRIFFITH , X & O . R38E T3S BA S11 1/4 S14 2019 **OPLS 83571**

UNION COUNTY **SURVEYOR**

File Number 013-2019 12

I used a Leica GS18 in the establishment of the new accessories. Basis of Bearing is as per Union County Survey 004-2019. The bearings and distances are to the center of the aluminum cap.