## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T3S R38E O-24

No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 024-2002.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 5/8"x30" iron pin with a 2 1/2" aluminum cap marked as shown below, 30" in the ground, from which:

NEW BEARING OBJECTS:

A 5/8"x30" iron pin set with 2" aluminum cap marked "BGB SURVEY MARKER NORTH RP", bears North 0°16'05" West, a distance of 30.00 ft.

A 5/8"x30" iron pin set with plastic cap marked "BGB SURVEY MARKER EAST RP", bears North  $89^{\circ}36'45$ " East, a distance of 30.00 ft.

I hereby certify that the corner was monumented on June 28, 2002. Witness: Greg Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OREGON
July 17, 1985
RICK G. ROBINSON
2219

Renewal Date December 31, 2002

T3S R38E

NE 1/16

+
S 24
2002

OPLS 2219

UNION COUNTY
SURVEYOR

Date Received 7/1/07

Date Filed 1/1/07

Filed By Hyr 4, Blue

File Number D66-2002 R

009-2002 R.

I used a Leica GPS System 500 instrument in the establishment of new accessories. The basis of bearing is the same as that of Survey Number 024-2002. The distances are to the center of the aluminum cap.

0-24