
## **UNION COUNTY SURVEYOR**

## **CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in Union County survey records.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey No. 015-2003

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 5/8" x 30" iron pin with a 2 ½" aluminum cap marked as shown below, 27" in the ground, from which:

New Bearing Objects:


A 5/8" x 30" iron pin with 1  $\frac{1}{2}$ " aluminum cap bears S 41°19'E, a distance of 22.60 feet, marked BGB SURVEY MARKER S26 RP. A  $5/8" \times 30"$  iron pin with 1 ½" aluminum cap bears S 19°59'W, a distance of

13.28 feet, marked BGB SURVEY MARKER S27 RP.

Set steel fence post approximately 3 feet South of monument.

I hereby certify that the corner was monumented on May 20, 2003.

Witness: Greg Blackman, Jr.



GRIFFITH T4S R38E S 1/16 2003 **OPLS 2219** 

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON

2219

I used a Leica 530 GPS unit in the establishment of the new accessories. The Basis of Bearing is the same as map of survey number 015-2003. The distances are to the center of a 5/8"x30" iron pin with 1 ½" aluminum cap.

U - 17Renewal Date December 31, 2004