CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-24

History of original corner establishment:
None

DIAGRAM

T5S R34E

E 1/16
C ← ← C
S24

Description of corner evidence found:

No monument or evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Cap is stamped:

Set steel fence post 3.0 ft. north of corner.

T5S R34E _E 1/16_

 $C\frac{E \ 1/16}{S24}C$ RLS 1844

1984

New BT's:

A 14" Tamarack bears NO.5°E, 33.0 ft., blazed and scribed: CE 1/16 S24 BT.

A 5" L. Pine bears S34 3/4°E, 12.5 ft., blazed and scribed: CE 1/16 S24 BT.

Painted blazes and attached signs as per <u>Standard</u> <u>Specifications</u> for <u>Cadastral</u> <u>Surveys</u>, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found in dense young L. Pine on north slope 1600 ft. south of Fly Creek. Road 5160-544 to Fly Creek , east along creek to posted property boundary.

I hereby certify the above described corner monument and/or accessories was established as described in June of 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

JULY 13, 1979

DAVID E. SCOTT

1844

Office of	County of		1077	222
State of	fy that the within instrument was a	filed in this o	fice UNION	COUNTY VEYOR
(COUNTY OFFICIAL)	. by(DEPUTY)	•••••		

Form R6-7100-57 (9/71)

Date Received 10-17-84

Date Filed 600-798-276

By G. LANGERTZ DEPUTY

File No. 957-84 R