## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

Form

Index File No. T-19

## DIAGRAM

T5S R34E C 1/4 • S26

Description of corner evidence found:

No corner monument or other official accessories found.

Description of monument and accessories I established to perpetuate the Cap is stamped: original location of this corner: T5S R34E Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 7" above ground. Set steel fence post C 1/4 · S26 3.0 ft. north of corner. RLS 1844 1984 New BT's: An 8" Tamarack bears N7.5°W, 37.2 ft., blazed and scribed: C 1/4 S26 BT. A 6" Fir bears S36 1/4°E, 6.1 ft., blazed and scribed: C 1/4 S26 BT. Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found at bottom of slope to west on small flat. Approximately 800 ft. west of Rd. 5160-196.
I hereby certify the above described corner

I hereby certify the above described corner monument and/or accessories was established as described on June 25, 1984.



File No. 966-84R

		1844
Office of	ounty of	
State of, I hereby certify that for record on the day of		this office UNION COUNTY SURVEYOR
(COUNTY OFFICIAL) (DEPUTY)		1
(COOKIT OFFICIAL)	(DEPUTY)	Date Received 10-17-84
R6-7100-57 (9/71)		Date Received 10-17-84  10-24-84  Date Filed GPO-798-276
		By G. LANGLITZ DEPUTY