


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-23

History of original corner establishment:

The original subdivision of T5S, R34E was by R. Moore under Contract No. 451, approved Feb. 1, 1884. He found a post, from which a 44" Pine bears N19°W, 53 lks. The township line between T5S and T6S had been surveyed by J. Cooper under Contract No. 397, approved April 5, 1882.



Description of corner evidence found:

No corner monument found. Found a 44" P. Pine snag dead & down, bearing N19°W, 35.0 ft. from corner, scribed (SC 1/4 S).

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Cap is stamped:
Set steel fence post 2.5 ft. north of corner.

SC
T5S R34E
1/4 S36
RLS 1844
1984

New BT's:

A 10" Juniper bears N22 1/4°E, 16.6 ft., blazed and scribed: SC 1/4 S36 BT.

A 5" P. Pine bears N29°W, 30.2 ft., blazed and scribed: SC 1/4 S36 BT.


Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 60 ft. above Little Fly Creek, on south slope 300 ft. west of Little Fly Creek and 500 ft. south of Road 5166-025.

I hereby certify the above described corner monument and/or accessories was established as described on June 21, 1984.



Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY SURVEYOR
Date Received 10-17-84
Date Filed 10-24-84
By G. LANGLITZ, Deputy
File No. 989-84 R