## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original G.L.O. corner.

Index File No. 0-0	7
DIAGRAM	
T5S R35E C	
N 1/16 S 20	
C	

Description of corner evidence found:

No corner evidence found.

Description of monument and accessories | established to perpetuate the Cap is stamped: original location of this corner:

Corner set by single proportioning.

T5S R35E

RLS 1844 1984

Set a 2.5" aluminum cap on 2"x30" aluminum pipe rising 6" above ground. Set steel fence post 2.0 ft. north of corner.

20 N 1/16+s

New BT's:

A 6" L. Pine bears N37.5°E, 58.6 ft., blazed and scribed: CN 1/16 S20 BT. a 6" L. Pine bears S75°E, 42.8 ft., blazed and scribed: CN 1/16 S20 BT.

Attached brass disk stamped LS 1844 to baze of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 1/2°E Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 6, 1984.

Corner is found 200 ft. north of intersection of roads 5155 and 5115, 70 ft. west of road 5115 at the fence.



Office of	nty of		
for record on the day of	within instrument was filed in this office . , 19	ribatade Rijon Cui.	114
(COUNTY OFFICIAL)	(DEPUTY)		
R6-7100-57 (9/71)		Path Received 1-23	-85

Form R