

The purpose of this survey was to establish the Southeast corner of the parcel along the North line of the old O.S.H.D. right of way, which was an extension of the North line of First Street.

A previous survey of 1967 located the SE corner 30 feet Northerly of the relocated highway center line. None of the original monuments were found in place. A concrete slab covers the original NW corner and the other three corner monuments were destroyed by farming activity.

A survey tie to the East end of the North rail of a spur track was utilized to reconstruct the basis for meridian and original corner locations. The 1967 survey from the 1½-inch steel pin marking the South ¼ corner of Section 34 to a brass disc located in the concrete bridge over the Grand Ronde River was assumed for the purpose of that survey to bear North.

The bridge has since been reconstructed, destroying the brass disc location. Another ¼ corner marker has been established by the O.S.II.D. in 1973 which bears N. 78° 12' W., 5.23 feet distant from the ¼ corner monument used prior to that date. This survey recognizes the true ¼ corner location as that previously used prior to the dual monumentation. A tie to the O.S.H.D. monument is shown here only for identification purposes.

The bearing from this recognized ¼ corner to the end of spur track (as it existed in 1967, it has since been extended) is N. 51° 35' 15" E., 630.52 feet, from which the Northwest corner of the parcel bears N. 80° 58' E., 47.98 feet distant. The parcel was relocated from the above data and monumentation, except for the aforementioned Southeast corner.