March 5, 1980

Smit Doe's Union Co. Surveyor

It is noted on survey by Oregon State Highway that it states I set the North $\frac{1}{4}$ corner of Section 3, T 3 S R 38 E WM.

This is completely untrue as this corner was in long before any work I have done, and I have records giving tie to corner in question dating sometime in early 30's.

This notation is completely false and is hereby so noted and this statement is made as attachment to reference survey.

Witness of signature

J. Dwain Spooner

OREGON STATE HIGHWAY DIVISION Plat of Conflict Between Original Island City - Cove Highway R/W and Ronde Valley Addition to Island City Union County

R.L. Feller, Resident Engineer February, 1973

Scale: 1"=100" 77 P.S. File 50729 NOTE: All I.P.s indicated as "I.P. set" were set 2/20/73. Survey was subsequently reviewed in 1979 and I.P.s as noted were recovered. <u>?sc</u> 10+68.8 P.C. I.P. set 0.S.H.D. R/W.