

REFERENCE MATERIAL

Survey Number 7-70 Survey Number 33-79 Survey Number 23-80 Survey Number 1-81

NOTE:

For monumentation information, see monumentation sheets filed separately.

BASIS OF BEARING

The East line of the Southeast quarter of Section 29 as being South 0°15′05″ West as per survey number 1-81.

LEGEND

Found aluminum monument set by survey number 1-81

Found monument as described

Set 21/2" x 30" aluminum pipe with aluminum cap at position determined by survey

Record bearing and distance of survey number 33-79.

Existing fenceline

NARRATIVE

This survey was done at the request of Chuck Sarrett, representing Boise Cascade Corporation. The purpose of this survey was to locate and monument the Southeast 1/16 corner of Section 29. I base my survey on survey number 1-81, which located the controlling corners of the Southeast quarter of Section 29. I find an existing East-West fenceline 96 feet North of the true 1/16 corner position. I find no other unusual conditions on this survey.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
RICK G. ROBINSON
2219



