

INCORPORATED. Our instructions were to establish and stake an easement 30 feet by 30 feet parallel to Indian Creek and Dutton Roads. I establish the two roads by splitting the fence lines along the existing right of way. I was also required to recover the Township corner on the Base Line. I began retracement of the Base Line at the Southwest Corner of Section 34 T I N. R. 39 E, and traversed East searching for corners along the way. I ended traverse at the Southwest corner of section 32 T I N. R. 40 E. I found a mound of stone at the Southeast corner of Section 36 and confirmed its position by the two found monuments East and West. I find that the sections to the West will average 5298.53 feet, while the sections to the East will average 5349.65 feet. The run to the East Is a much more difficult run topographically. I find no other problems with this survey.

REFERENCE MATERIAL

Survey Number 28-89

UNION COUNTY SURVEYOR

Date Received 4-27-90 Date Filed 5-5-90 File No. 14-90

MEGISTERED **PROFESSIONAL** LAND SURVEYOR



Map of Survey
An easement located in the Northwest 1/4
of the Southeast 1/4 of Section 36 Township
I North, Range 39 East of the Willamette Meridian.

UNION COUNTY, OREGON

SURVEYED FOR GTE SURVEYED BY GTB 4-90 Scale: |" = 20" Drawn by: JPP 4-20-90

Fenceline

Centerline

BASIS OF BEARING

Solar observation taken at a point 2856.26 feet South and 497.46 feet East of the Northwest corner of Section 3, Township I South, Range 39 East of the Willamette Meridian. (Same basis of bearing as survey no. 28–89.)

Overhead powerline

Set 21/2" × 30" aluminum monument from original GLO evidence.

Set $5/8" \times 30"$ Iron pin with plastic cap marked BGA SURVEY MARKER,

Found 2 1/2"x 30" monument set from-original GLO evidence.

NOTE:

0

0

•

Union County Roadmaster , Richard Comstock states that there is no immediate plans for road improvement or widening of road right of way, May 15, 1990.

OREGON GREGORY T. BLACKMAN

<u>991</u>