

BASIS OF BEARING

Solar observation taken at the Southwest corner of Section 15, Township 3 South, Range 40 East of the Willamette Meridian.

SCALE: 1"=100'

REFERENCE MATERIAL

Union County Monumentation Records Plat of Vista Acres Subdivision Survey Number 15-84 Survey Number 031-1995 Minor Partition Plat Number 1995-21 Minor Partition Plat Number 1996-12 Minor Partition Plat Number 2001-10

DEED REFERENCES

Deed Volume 144 Page 66 Deed Volume 144, Page 253 Microfilm Number 41819 Microfilm Number 42740 Microfilm Number 115244

<u>Curve</u> Data

R/W North Curve

North of Adjustment Centerline
North Curve △= 4473'41" △= 24°23'00" A = 2423 00' R = 260.00' L = 110.65' T = 56.17' L.C. = 109.82' N 51'31'39"W R = 230.00' L = 177.54' T = 93.46' L.C. = 173.17' N 41°36'19"W R/W North Curve Centerline
Southwest Curve

Within Adjustment $\triangle = 19.50.41$ " R = 260.00L = 90.05' T = 45.48'

 \triangle = 59'50'07" R = 401.96' L = 419.78' T = 231.30' L.C. = 400.96' L.C. = 89.60'N 29'24'48"W Right of Way Right of Way Southeast Curve

(5) Southwest Curve $\triangle = 59^{\circ}50'07''$ R = 371.96'L = 388.45'T = 214.04'L.C. = 371.03' N 49'24'24"W

 $\triangle = 5'11'07''$ R = 1834.17'L = 166.00' T = 83.05' L.C. = 165.94' N 81°55'16"W

N 49°24'24"W

Centerline Southeast Curve △= 8°08'01" R = 1864.17'L = 264.63' T = 132.54' L.C. = 264.41' N 83'23'43"W

R/W Southeast Curve East of Adjustment \triangle = 2°56′54″ R = 1834.17′ L = 94.38′ T = 47.20′ L.C. = 94.37′ N 85°59′16″W

LEGEND

Found aluminum monument as per Union County monumentation records

Found 1/2" iron pin with plastic cap marked LS 934 set by survey number 15-84

Found 5/8" iron pin with plastic cap marked BGB SURVEY MARKER set by survey number 031-1995

Found 5/8" iron pin with plastic cap marked BGB SURVEY MARKER set by Minor Partition Plat Number 1995-21

Found 5/8" iron pin with plastic cap marked AP&A set by Minor Partition Plat Number 1996-12

Found 5/8" iron pin with plastic cap marked BGB SURVEY MARKER set by Minor Partition Plat Number 2001-10

Found 5/8" iron pin with plastic cap marked BGA SURVEY MARKER set by the Plat of Vista Acres Subdivision

Set 5/8"x30" iron pin with plastic cap marked "BGB SURVEY MARKER"

Centerline of road

Existing fence line

Irrigation Ditch

Easement

Existing gravel roadway

NARRATIVE

This survey was done at the request of Silas Martin. The purpose of this survey is to monument a lot line adjustment between the Martin Family Trust, owners of Parcel 2 of Minor Partition Plat Number 1995-21, and the Eastern Oregon Convention of Christian Churches, owners of the adjacent tract to the South. The exterior of the Church tract was determined by the compilation of the adjacent surveys, partitions, and the plat of Vista Acres Subdivision. No monuments were set on this survey except the two which determine the adjusted property line. They were placed at the direction of Mr. Martin. find the existing fence to be away from the true property lines as shown. I find no other unusual conditions on this survey.

> REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON JULY 17, 1986 RICK G. ROBINSON 2219

Renewal Date: Dec. 31, 2002

♣ BAGETT, GRIFFITH & BLACKMAN 2006 Adams Avenue, LaGrande, Oregon

Lot Line Adjustment situated in the SE 1/4 of the SE 1/4 of Section 22, and in the SW 1/4 of the SW 1/4 of Section 23, Township 3 South, Range 40 East of the Willamette Meridian.

Map of Survey

	THOIT COOKER, CILCOIT		ı
SURVEYED FOR	Silas Martin		l
SURVEYED BY	R.G.R.	4/02	I
Scale: 1" = 100'	Drawn by: R.G.R.	4/02	

UNION COUNTY SURVEYOR Date Received 4/08/02 009-2002