

Township 7 South Range 41 East Union County, Oregon.

- 39 75 Thence East
The center Sec 11 Set Post dug Pit's built mound &c
The 1/4 Sec corner bet Sec 2 & 11
Thence South
- 20 03 Set Post for 1/16 cor
- 40 06 The center Sec 11
- 60 09 Set Post for 1/16 cor
- 40 11 The 1/4 Sec cor on bet Sec 11 & 14
The 1/4 Sec corner bet Sec 11 & 12
Thence East through Sec 12
- 20 50 Set Temporary 1/16 corner
- 40 50 Set Temporary center Sec 12
- 80 18 Intersect East Bdy at 1/4 Sec corner bet Sec 7 & 12
The 1/4 Sec cor bet Sec 1 & 12
Thence South var 20° E
- 20 50 Set Temporary 1/16 corner
- 40 38 Intersect E & W line 18.40 East of 1st Stake at center
- 60 38 Set Temporary 1/16 corner
- 80 76 Intersect South boundary found no 1/4 Sec cor Set Temporary Post
I then proceeded to the corner by Sec 11 = 12 = 13 & 14
Thence East var 20° E
- 39 43 Set Temporary 1/4 Sec cor
- 80 30 Intersect Range line at corner to Sec 12 = 13 = 7 & 18
Thence west
- 40 15 Set Stone 6 x 10 x 20 in (mid of Stone for 1/4 Sec cor
Thence North
- 20 19 Set Post for 1/16 corner
- 40 38 Set Post in mound of Stone for center Sec 16
- 60 59 Set Post for 1/16 corner
- 80 76 The 1/4 Sec cor bet Sec 1 & 12
The 1/8 cor on west Bdy NW 1/4 Sec 12
Thence East
- 20 00 Set Temporary 1/16 cor
- 40 18 The 1/16 cor in center N 1/2 Sec 12
Thence west
- 20 09 Set Post for center NW 1/4 Sec 12
Thence South
- 20 17 Set Post for 1/16 corner in center NW Sec 12

J. W. Tomball Deputy Co. Surveyor