

RECORD OF SURVEY

Township 8 South

Range 46 East

Union County, Oregon.

CHAINS. LKS.

- 59 70 Set Post for center W 1/2 Sec 4 - from which
a cottonwood 8 in dia. has S 88° W 253 lks
thence South
- 29 07 Set Post for 1/6 corner in center S W 1/4 Sec 5 - from which
a cottonwood 4 inch dia has S 28° W 35 lks dist.
The 1/4 Sec corner bet Sec 5 & 8
thence North through Sec 5 - bearing 20° E
- 20 00 Set temporary 1/6 corner
40 00 Intersect E & W line
60 00 Set temporary 1/6 corner
- 78 58 The 1/4 Sec corner bet Sec 5 & 32 thence South
- 18 30 Set Post for 1/6 corner from which
a cottonwood 20 inch dia has S 46 3/4° W 71 lks dist.
- The corner to Sec. 7-8-17 & 18
thence East bearing 20° E
- 40 13 The 1/4 Sec corner bet Sec 8 & 17
thence West on line
- 20 06 1/2 Set Post for 1/8 corner
thence North bearing 25° E
- 20 00 Set Post for temporary 1/6 corner
40 00 Set temporary center W 1/2 Sec 8
60 00 Set temporary 1/6 corner
80 23 Intersect North boundary 40 lks East of 1/8 corner
on North boundary N W 1/4 Sec 8
thence South on line
- 20 05 Set Post for 1/6 corner in center N. W 1/4 Sec 5 -
4 011 Set Post for 1/6 corner in center W 1/2 Sec 8
60 17 Set Post for 1/6 corner in center S W 1/4 Sec 8

J. W. Fairbairn Sept. County Surveyor