



Township

Range

Union County, Oregon.

CHAINS.	LKS.	
20	25	Set a stone for $\frac{1}{16}$ Corner
40	50	The stone as set by me in running East from $\frac{1}{4}$ Sec Cor
60	90	Set a stone for $\frac{1}{16}$ Corner
81	40	The $\frac{1}{8}$ Corner as set by Kimball. Then I run South from $\frac{1}{8}$ on the North Side of the N.E $\frac{1}{4}$ Sec. 30
20	25	Set a stone for $\frac{1}{16}$ Corner
40	50	" " " " $\frac{1}{16}$ "
61	65	" " " " $\frac{1}{16}$ "
82	80	The $\frac{1}{8}$ Corner as set by Kimball The Government Corners could all be identified by Government field Notes held by me

Arthur Curtis  
County Surveyor