

RECORD OF SURVEY

Township *Five South* Range *Forty E.W.M.* Union County, Oregon.

CHAINS. LKS.

Survey made June 25, 1913, for S. J. Godsey et al.
1/4 Cor East side - Established by witness trees and testimony of Harry Rodman. Marked stone 1/4 and bedded firmly in ground. measured due west (N. 19°45' E.) 5292' to 1/4 Cor.

1/4 Cor West side Established by Bearing tree and old fence corner. (I marked stone 1/4 and firmly planted it in ground.)

Begin 1/4 Cor East side and measured 2728 feet to Cor. at S.E. of sec.

S.E. Cor. Established by pile of stone and testimony Harry Rodman and his Father. (I marked stone and planted firmly in ground)

S.E. Cor measured west 2646 feet to 1/4 Cor south side. Established this corner from Bearing tree. (I set stone marked 1/4) and measured north 2785 feet to center of sec. or middle of East and West line from 1/4 Cor. West to 1/4 Cor. East.

Set stone marked C.S. at this center.

Survey made by C.T. Darley County Surveyor.

Recorded July 1st by C.T.D.

Those present Harry Rodman, S. J. Godsey, Q. D. Morgan, Louis Lacer, and C.T. Darley

