

Field Notes of the
Survey of the Ditch owned by
La Grande Irrigation Co.

Commencing at a point North 56° West 546 feet from the South West Cor of Blk 69 Riverside Add. to La Grande, Or. on the South bank of Grande Ronde River Then South 62° East 20 feet; Then South 88° East 1000 ft. Then South 35° East 220 feet to East side of Unatilla St

"	"	2°	"	490	"	"	North	"	of Lake St
"	East			450	"	"	"	"	"
"	South	43°	East	60	"	"	South	"	side of Lake St
"	East			1310	"	"	East	"	" 1st "
"	South			260	"	"	a point 5 ft west of S.W. Cor	"	Blk 9 ^{Ad.}
"	"	$3^{\circ} 30'$	East	113	"	"	"	"	"
"	"	$41^{\circ} 30'$	"	50	"	"	"	"	"
"	"	$21^{\circ} 30'$	"	100	"	"	"	"	"
"	"	46°	"	100	"	"	"	"	"
"	"	$67^{\circ} 30'$	"	140	"	"	"	"	"
"	North	71°	"	100	"	"	"	"	"
"	"	40°	"	100	"	"	"	"	"
"	South	85°	"	100	"	"	"	"	"
"	"	70°	"	100	"	"	"	"	"
"	North	$87^{\circ} 30'$	"	100	"	"	"	"	"
"	"	89°	"	100	"	"	"	"	"
"	South	79°	"	100	"	"	"	"	"
"	"	25°	"	85	"	"	to East side of 4th St.	"	Chapline ^{Ad.}
"	North	81°	"	125	"	"	"	"	"
"	South			453	"	"	feet along East line of 4th St	"	to line between Blk 157-166
									Chapline Supplementary Add