CORNER REFERENCE INDEX

EXAMPLE

REFERENCE NO.	EXPLANATION
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

10-83R
- 83 — year filed
- 10 — file no.

T 1N, R 39 E

S5	S4
S8	S9

REFERENCE NO.	NOTES & DESCRIPTION	
SURVEY # 26-70	———	VOELZ - 1970
Survey #030-1993	Corner set.	Robinson 1993
027-1993R	monumentation Record.	Robinson 1993
SURVEY #017-1993	FOUND AC IN WATER VALVE BOX	ROBINSON-1994
SURVEY 032-1997	FND ALUMINUM MONUMENT IN WATER VALVE BOX	ROBINSON-1997
SURVEY 020-2006	FND A/C IN WATER VALVE BOX	ROBINSON-2006
SURVEY 032-2012	FND ALUMINUM MONUMENT IN WATER VALVE BOX	HSU-2012
SURVEY 022-2017	FND ALUMINUM MONUMENT	HSU-2017
SURVEY 036-2021	FND ALUMINUM MONUMENT	HSU-2021
SURVEY 016-2023	FND ALUMINUM MONUMENT	HSU-2023
SURVEY 018-2024	FND ALUM. MONUMENT	HSU-2024
SURVEY 019-2024	FND ALUM. MONUMENT	HSU-2024

CORNER LOCATION CODE E9