CORNER REFERENCE INDEX

EXAMPLE

REFERENCE NO.	EXPLANATION
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

10-83R
- 83 — year filed
- 10 — file no.

T 35 , R 38 E

S10
1/4
S15

REFERENCE NO.	NOTES & DESCRIPTION	
Survey # 37-71	FD Conc Nail	Griffith - 1971
Survey # 48-71	———	Voelz - 1971
Survey # 76-71	Steel Nail	Voelz - 1971
Survey # 78-71A	Steel Nail	Voelz - 1971
Survey # 72-72	———	Voelz - 1972
Survey # 41-72	Found Steel Nail	Voelz - 1973
Survey # 11-74	Found Steel Nail	Voelz - 1974
Survey # 104-74	Steel Nail Not Found (Assumed Destroyed)	Voelz - 1974
Survey # 43-77	Found Concrete Nail	Blackman - 1977
Survey # 122-78	Found Conc. Nail	Stabler - 1978
Survey # 19-85	Projected Position per Survey 48-71, no prior	
~~50-85R~~	Monument found.	Langlitz-1985
50-85R	Monumentation Record	Langlitz-1985
045-1996R	Set 2½" x 30" aluminum pipe monument	Blackman '96
GPS #9636	GPS Observation (attached)	Caswell - 1996
Survey 039-2002	Fnd PLSS corner, Replaces Comm	McLennon-2002
041-2002R	Corner Remon New mon. & R.P's	McLendon 2002
Survey 028-2014	Found 3" Brass Cap	Butler 2014
Survey 029-2017	Found Brass Cap	Elithorp-2017

CORNER LOCATION CODE 4-15