


CORNER REFERENCE INDEX

EXAMPLE

<u>REFERENCE NO.</u>	<u>EXPLANATION</u>
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

year filed
file no.



<u>REFERENCE NO.</u>	<u>NOTES & DESCRIPTION</u>
SURVEY # 43-77	SET 5/8" IRON ROD BLACKMAN - 1977
SURVEY # 122-78	FOUND 5/8" PIN STABLER - 1978
SURVEY # 43-84	FD. 5/8" REBAR PER SURVEY 43-77 PAULLUS - 1984
SURVEY # 19-85	FD. 5/8" REBAR PER SURVEY 43-77 LANGLITZ - 1985
27-85R	VISITATION PAULLUS - 1989
52-85R	VISITATION LANGLITZ - 1985
SURVEY 007-1996	FND 1" REBAR PAULLUS - 1996
044-1996R	Set 2 1/2" x 30" aluminum pipe monument Blackman '96
GPS # 9637	GPS OBSERVATION (ATTACHED) CASWELL 1996
SURVEY 014-2002	FND 2 1/2" ALUM PIPE MONUMENT ELDER [REDACTED] - 2002
SURVEY 034-2012	MONUMENT DESTROYED BY GAS CONSTRUCTION BATTEN - 2012
026-2012R	MONUMENTATION RECORD ROBINSON - 2012
GPS 201209	GPS OBSERVATION ROBINSON - 2012
MP 201300107	FND 2 1/2" ALUMINUM PIPE MONUMENT ELDER - 2013
SURVEY 004-2019	FND 2 1/2" ALUMINUM MONUMENT HSU - 2019

CORNER LOCATION CODE 5-17