


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-13
~~7-13~~

History of original corner establishment:



4'x4sq. IN. POST 2' IN THE GROUND

16" FIR N25E 22LKS. MKD. T2N R38E S34 BT
 5" FIR N30W 22LKS. MKD. T2N R38E S33 BT
 6" FIR S55E 26LKS. MKD. TIN R38E S3 BT
 12" FIR S70W 32LKS. MKD. TIN R38E S4 BT

Description of corner evidence found:

RED PAINTED STAKE

22" FIR S70W 21.1' SCRIBING VISIBLE
 22" FIR N25E 14.5' UNOPENED SNAG

Description of monument and accessories established to perpetuate the original location of this corner:

SET A 2"x30" IRON PIPE WITH BRASS-CAP MARKED: T2N R38E
 S33 S34
 S4 S3
 TIN
 1978
 RLS 346


14" FIR S25E 22.4' MKD. TIN R38E S3 BT
 10" FIR N17W 38.4' MKD. T2N R38E S33 BT
 8" FIR N88E 28.3' MKD. T2N R38E S34 BT

ALL BT'S HAVE A RED PAINTED STRIPE AND BT SIGNS. THE NEW BT'S HAVE A BRASS WASHER STAMPED RLS 346 NAILED TO THE LOWER FACE. THERE IS A 6' STEEL FENCE POST WITHIN 5' OF THE CORNER.

Office of..... COUNTY SURVEYOR..... County of..... UNION.....

State of..... OREGON....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by..... (COUNTY OFFICIAL) (DEPUTY)



UNION COUNTY SURVEYOR

Date Received # GPO-700-246

Date Filed

By

File No. 9-84R