


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-19
~~Z-19~~

History of original corner establishment:



WOODEN POST

6" TAMARACK S40W 9 LKS. MARKED 1/4 S BT
8" TAMARACK N40W 10 LKS. MARKED 1/4 S BT

Description of corner evidence found:

10" LARCH
18" LARCH

SCRIBING VISIBLE IN BOTH TREES.

Description of monument and accessories established to perpetuate the original location of this corner


SET A 2"x30" IRON PIPE WITH A BRASS-CAP MARKED:

T2N R38E
S35
1/4 S2
T1N
1978 46
RLS 346

THE CORNER IS SET AT THE RECORD DISTANCE FROM EACH TREE. THE BEARINGS TO THE ORIGINAL BT'S HAVE CHANGED TO S77W AND N14E.

SET: 16" LARCH N32E 20.6' MKD. 1/4 S35 BT
16" LARCH N11W 28.1' MKD. 1/4 S2 BT

ALL BT'S HAVE A RED PAINTED STRIPE AND BT SIGNS. THE NEW BT'S HAVE A BRASS WASHER STAMPED RLS 346 NAILED TO THE LOWER BLAZE.



Wayne O. Harris
MAY 6, 1968
WAYNE O. HARRIS
346

Office of COUNTY SURVEYOR County of UNION

State of OREGON, I hereby certify that the within instrument is a true and correct copy of the original as shown to me by the SURVEYOR

for record on the day of by (COUNTY OFFICIAL) (DEPUTY)

Date Received _____
Date Filed _____
By _____
File No. 14-84R